


**DESCRIPTION**


|                          |                         |          |
|--------------------------|-------------------------|----------|
| Project Name:            | Condo San Bernardo      |          |
| Section Name:            | Losa casa 1             |          |
| Sensor Name:             | Sensor 1                |          |
| Location:                | San Bernardo            |          |
| Tagged By:               | JP                      |          |
| Pouring Time:            | 05/10/2017 4:40 PM      |          |
| Mix ID:                  | HB20 Ready Mix          |          |
| Maturity Method:         | Temperature Time Factor |          |
| Datum Temperature:       | 0.0°C                   |          |
| Calibration coefficient: | a= -81.69               | b= 39.86 |
| Comments:                |                         |          |




**TEST RESULTS**

|                  |             |
|------------------|-------------|
| Max Temperature: | 20.8 °C     |
| Min Temperature: | 1.1 °C      |
| Maturity Index:  | 6315 °C-hrs |
| Strength:        | 69.8 MPa    |


**TEMPERATURE**



**MATURITY**



**STRENGTH**



signature